

BRIDGE INSPECTION REPORT

For Bridges other than Trunk Road or Motorway Bridges

DISTRICT OLDHAM

Bridge Name BROOKDALE F/B Bridge No. 06/459 Date 6/3/96

Road No. N/A Road Name N/A permissive path Spanning River Tame

Condition of Part	G F P	Condition of Part	G F P	Condition of Part	G F P
1. Invert	G	13. Expansion Joints	/	25. Spandrel Walls	/
2. Aprons	/	14. Main Beams	G	26. Tie Rods	/
3. Foundations	N/V	15. Encased Ends	/	27. Pointing	G
4. Cutwaters	/	16. Troughing	/	28. Condition of Masonry	G
5. Piers/Columns	/	17. Jack Arches	/	29. Surfacing	/
6. Abutments	G	18. Transverse Beams & Diaphragms	G	30. Coping	/
7. Wing Walls	/	19. Waterproofing	/	31. Pilasters	/
8. Embankments	/	20. Drainage Superstructure	/	32. Scour	None
9. Training Walls	/	21. Concrete Deck <u>WOODEN</u>	G	33. Paintwork	D
10. Drainage Substructure	/	22. Arch Springing	/	34. Stringcourse	/
11. Parapets	/	23. Arch Ring	/	35. Parapet Railings	F
12. Bearings	N/V	24. Voussoirs/Arch Face	/	36.	

Remarks (Refer to parts by above numbers).

(33) The whole structure (could) do with painting
 (35) The right hand entrance upright (on the parapet) North facing
 is loose from its bolts and may need future repair
 T. Cavanagh confirmed that this structure is on a permissive
 path and responsibility of Leisure Services.
 please advise

Street Ref: LD1

G.A. Assistant Bridge Superintendent

D. Martin Bridge Superintendent

Remedial work recommended at previous inspection satisfactorily completed. YES NO

Comments if answer is NO.